



Solution details		Sentera products	
<p>The AC fan will be controlled manually via the five steps transformer fan speed controller STR.</p> <p>Suited for motor type: 400 VAC voltage controllable motors Motor control: Transformer fan speed controller Minimum motor speed: Make sure that the minimum voltage remains high enough to avoid stalling of the motor. Maximum motor current: 11 A</p> <p> Consult the fan manufacturer for the correct wiring</p>		Article code	Description
		STR-4110L40	Transformer fan speed controller
		External products	
		AC fan with a voltage controllable motor I _{max} 11 A	