




Solution details

The rotational speed of the fan can be manually controlled via the potentiometer.
TK monitoring for thermal motor protection.

Suited for motor type: 400 VAC voltage controllable motors with TK motor protection
Motor control: Transformer fan speed controller
Minimum motor speed: Make sure that the minimum voltage remains high enough to avoid stalling of the motor.
Maximum motor current: 4 A

 Consult the fan manufacturer for the correct wiring

Sentera products

Article code	Description
MTP-X10K-NA STVS4-40L40	Fan control potentiometer Transformer fan speed controller

External products

AC fan with a voltage controllable motor I_{max} 4 A