

 \triangle Consult the fan manufacturer for the correct wiring.

Sentera products		External products	Parameters settings			
Article codes	Description	AC motor 10 A	Article codes	Parameters	Values	Descriptions
	Remote variable speed control for AC fans with single-phase motor. The maximum motor current is 10 A. The fan speed controller can be installed on a DIN rail. Via the external potentiometer, fan speed can be set. At zero position, the motor stops. The cable length between potentiometer and fan speed controller should remain limited to avoid disturbances of the 0-10 V signal.					
This document is to be treated as an example or guideline only. Sentera bears no responsibility for any misprints, misinterpretations or mistakes in this document. Consult our disclaimer on https://www.sentera.eu/						



Solution ID: FS-R-000091