



Solution details

The AC fan will be controlled manually via the five steps transformer fan speed controller STR.

Suited for motor type: 400 VAC voltage controllable motors  
Motor control: Transformer fan speed controller  
Minimum motor speed: Make sure that the minimum voltage remains high enough to avoid stalling of the motor.  
Maximum motor current: 6 A

 Consult the fan manufacturer for the correct wiring

Sentera products

Article code	Description
STR-4-60L40	Transformer fan speed controller

External products

AC fan with a voltage controllable motor I<sub>max</sub> 6 A