




Solution details

The AC fan will be controlled via the transformer fan speed controller STRA4.
The external contact for activate the fan (Available NO and NC contact).
TK monitoring for thermal motor protection.

Suited for motor type: 400 VAC voltage controllable motors
Motor control: Transformer fan speed controller
Minimum motor speed: Make sure that the minimum voltage remains high enough to avoid stalling of the motor.
Maximum motor current: 2,5 A

 Consult the fan manufacturer for the correct wiring

Sentera products

Article code	Description
STRA4-25L40	Transformer fan speed controller

External products

AC fan with a voltage controllable motor I_{max} 2,5 A