



Solution details		Sentera products	
<p>The rotational speed of the fan can be manually controlled via the potentiometer. TK monitoring for thermal motor protection.</p> <p>Suited for motor type: 400 VAC voltage controllable motors with TK motor protection                      Motor control: Transformer fan speed controller                      Minimum motor speed: Make sure that the minimum voltage remains high enough to avoid stalling of the motor.                      Maximum motor current: 8 A</p>		<p><b>Article code</b></p> <p>MTP-X10K-NA STVS4-80L40</p>	<p><b>Description</b></p> <p>Fan control potentiometer Transformer fan speed controller</p>
		External products	
		AC fan with a voltage controllable motor I <sub>max</sub> 8 A	

Consult the fan manufacturer for the correct wiring