



Solution details The AC fan will be controlled manually via the five steps transformer fan speed controller with thermomagnetic breaker STTA. The external contact activates the fan. (Available NO and NC contact). TK monitoring for thermal motor protection. Suited for motor type: Motor control: Minimum motor speed: Make sure that the minimum voltage remains high enough to avoid stalling of the motor. Maximum motor current: AC fan with a voltage controllable motor lmax 11 A Consult the fan manufacturer for the correct wiring